REF: COR/2020/0080 - LISTED BUILDING CONSENT APPLICATION, APRIL 2021 - DOCUMENT D
8 TAMWORTH STREET, DUFFIELD, DE56 4ER (Grade 2 Listing: 1158259)
Disrepair and incorrect installation of 'Tulip' design panels.

DANGEROUS CONDITION (BELOW 3 PHOTOS AND RIGHT): evidence of pronounced outward bowing and crack across the lower green glass portion.












POOR QUALITY (ABOVE): detail of poor quality leading and construction. Note central cross piece not considered in the design. 'Off the shelf' art nouveau style tulip motif holds no local or historical period relevance.



POOR INSTALLATION (RIGHT): existing tulip motif panels; incorrectly installed as non-mirroring design, and note difference in height of flowerheads.

photographs © Mitchell, 2021