Specification:

Flashings. There is an intention to repair the horizontal part of the pediment and as such does not form part of this application as oit is for the partial replacement of the stone not any repairs.

The paint system we would adopt would be a mineral based paint (probably Keim external paint system) as suggested by the heritage Officer, should the overall replacement be unsatisfactory.

The source of the stone, as agreed by the Heritage Officer would be Howley Park from Hutton Stone.