MATERIALS:


WALLS: COURSED GRITSTONE MATCHING EXISTING.
MORTAR JOINTS IN CEMENT LIME SAND 1:1:6
WITH BRUSHED BACK FLUSH POINTING.
NATURAL GRITSTONE HEADS.

ROOF: STAFFS. BLUE CLAY TILE MATCHING EXISTING.

RAIN GOODS: BLACK PAINTED CAST METAL
ON RISE AND FALL BRACKETS MATCHING EXISTING.
NO FASCIA OR BARGE BOARDS.

PERSONNEL DOOR: LIGHT STAINED TIMBER RECESSED 75MM IN REBATE.


GARAGE DOOR: PAINTED ROLLER SHUTTER.



REAR



FRONT



SIDE

PROPOSED ELEVATIONS
Scale 1 : 100