

Direction of lean to mid point of property



View of lean to the South-East taken facing West



Area of root plate showing lift/ground heave towards the North-West side of trunk, Picture taken facing South-West



View of lean to the South-East facing North