
Footprint of former Chrysallis bungalow
SITE AREA 686.8sqm
A-A
A-A
WINDLEY LANE
WINDLEY LANE
THE LITTLE HOUSE
GARAGE
Grass
Planted
Gravel
Setts
Tarmac
Building Rubble Remains
Concrete Retaining Wall
Hedge
Fence
Ridge
Eave
Trees
Vegetation
Stump
Tank
Paving
Unstable wooden fence
Centre of roadway was adjacent wall in 1960's
Overhead Line
Electric Cable
Stone Slab
Manhole
Drain
Gully
Inspection Chamber
Soil Vent Pipe
Rainwater Pipe
Gas Valve
Water Valve
Electric Box
Telephone Box
Post
Sign
Bollard
Kerb
Channel
Edge
Concrete
Slope
Bank
Ditch
Culvert
Catchpit
Soakaway
Chamber
Cover
Level
Invert
Building Rubble Remains
Concrete Retaining Wall
Concrete Retaining Wall
Concrete Retaining Wall