Plan to be read in conjunction with Tree Survey Schedule and associated report (Ref: JH0826CHURCHCL).
The original of this drawing was produced in colour - a monochrome copy should not be relied upon.

CHURCH CLOSE

3

2

1

Garden would likely have been dominated by removed tree. Stem diameter indicates that potential development in area, by other roots, would have been limited.

H2

St6

T1

H4

H5

T3

N

0m 5 10 15m

Key & Notes	Cat C Trees & Groups	W1,W2,W3 etc... Woodland Tag	Shade Segment	Ground Protection Areas	FSB Direction	Date: August 2026	Plan to be read with associated report.	Outline Trees Arboricultural Consultancy 4 Kings Drive Littleover Derby
Cat A Trees & Groups	Cat U Trees & Groups	B1, B2, B3, B4 etc... Shrub Tag	H1, H2, H3 etc... Hedgerow Tag	Specialized Foundations	Title: Existing Tree Survey Plan		DWG:JH- TSP - 1 of 1	
Cat B Trees & Groups	Trees/Groups for removal	Hedgerows	No-dig Surfacing Areas	Fencing Location / RPA Extent	Site: 3 Church Close, Smalley, Ilkeston DE7 6JX		1:200 @A3	